



WARNING

5/16/2008

No PPE Available Energized Work Prohibited

3' - 11.4" Flash Hazard Boundry
412.8 cal/cm² Flash Hazard at 18 Inches
N/A PPE Level
No PPE Available

13.2kV Voltage Shock Hazard When Cover Is Removed
0' - 0" Limited Approach
0' - 0" Restricted Approach
0' - 0" Prohibited Approach

Equipment: Sub-Station Transformer



WARNING

5/16/2008

Arc Flash and Shock Hazard Appropriate PPE Required

1' - 9.8" Flash Hazard Boundry
30.8 cal/cm² Flash Hazard at 18 Inches
#4 PPE Level
Cotton Underwear + FR Shirt & Pants + Multi Layer Flash Suit

480V Voltage Shock Hazard When Cover Is Removed
0' - 8.4" Limited Approach
0' - 4.8" Restricted Approach
0' - 3.8" Prohibited Approach

Equipment: MDP

